

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C




FIG 6A





FIG. 6B





FIG. 6C





FIG. 7A

66	IDLE
65	IDLE
64	IDLE
63	ALU-3
62	ALU-2
61	IDLE

24 ~ ALU-1

FIG. 7B

66	IDLE
65	IDLE
64	IDLE
63	ALU-3
62	ALU-2
61	IDLE

24 ~

FIG. 7C

66	IDLE
65	IDLE
64	IDLE
63	IDLE
62	ALU-3
61	ALU-2

24 ~ ALU-2

FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14

